

[illegible]

[illegible]

[illegible]

[illegible]

Train #	Car #	TC1	M1	M2	M3	M4	TC2	Process Stage	Inspector	Date	Page			
200	N12								Bern/bocky	4/24/24	1 of 1			
Item	Defect Code	Demerit Class	Description of Defects						Localisation Interior, underframe, roof etc.	End [1] or [2]	Side Left [L] or Right [R]	Action Required (Ready to fix/Part needed/ NCR/ Work Instruction required for special process rework)	Quality Sign-off	Prasa Sign-off
1			Rust on Euf 1 LHS											
2			Paint damage by 14th							1-2 L+R	R/L			
3			Paint Mismatch on Euf							2				
			Poor Sealant joint on Finisher LHS Euf 1											

GIBELI

GIB000000380

Rev A0

Defects Report

29/03/2017

4/5 Pages

[illegible]